

Changes to the fourth edition following January 2019 update

Section Page Amendment

Separating Wall – Masonry

E-WM-9

Checklist 6 Points 7 & 8 adjusted to read “cement:sand render”.

Separating Wall – Timber

E-WT-2

First bullet point 1 Clarification to show all acceptable sheathing options.

DO box 1 2nd bullet point reworded.

Checklist 8 New item 3 added; subsequent items renumbered.

Separating Wall – Steel

E-WS-1

Diagram 1 2 Fusion Thermashield added as a flanking option
Note added referencing separating floors and Table 3c.

Diagram 2 2 Fusion Thermashield added as a flanking option
Note added referencing separating floors and Table 3c.

Checklist 8 New item 6 added; subsequent items renumbered.

E-WS-5

Diagram 11.2 10 Service void specification corrected to read “1 layer of gypsum board”.

Separating Floor – Concrete

E-FC-5

Contact details 6 Resilient system corrected to read “YELOfon® HD10+”.

Separating Floor – Steel

E-FS-3

Diagram 1 2 Option added to space gypsum board lining off Fusion Thermashield.

Ceiling treatments 4 New CT1 and CT2 options added to allow use of generic resilient bar.

Checklist 6 Item 6 reworded to cover ceiling treatment options.
New items 10 & 11 added; subsequent items renumbered.
Collecta contact details updated.

Appendix A2

Icopal-MONARFLOOR BRIDGESTOP 2 Description of item 4 amended to reflect revised component name.

